



TABELA DOBORU FREZÓW VHM / SOLID CARBIDE END MILLS SELECTION TABLE

STL			INOX		AL								
R430	R230L	R430L	R345	245	R245	345	R345	B245	B345	445	R445		
Z	4	2	4	3	2	2	3	2	3	4	4		
	VHM TiAlN	VHM TiAlN	VHM TiAlN	VHM TiAlN	VHM - / TiB ₂	VHM - / TiB ₂	VHM - / TiB ₂	VHM TiB ₂	VHM TiB ₂	VHM -	VHM -		
Strona / Page	HA	24	25	26	29-30	33-36	33-36	37-40	37-40	41	42	43-44	43-44
	HB	24	25	26	29-30	33-36	33-36	37-40	37-40	41	42	43-44	43-44
	Vc/fz	83	84	85	86	87	87	88	88	89	90	91	91

P1	●	●	●	○									P1
P2	●	●	●	○									P2
P3	●	●	●	○									P3
P4	●	●	●	○									P4
P5	●	●	●	○									P5
P6	●	●	●	○									P6
P7	●	●	●	○									P7
P8	●	●	●	○									P8
P9	●	●	●	○									P9
P10	●	●	●	○									P10
P11	●	●	●	○									P11
P12	●	●	●	○									P12
P13	●	●	●	●									P13
P14	●	●	●	●									P14

M1				●									M1
M2					●								M2
M3				●									M3

K1													K1
K2													K2
K3													K3
K4													K4
K5													K5
K6													K6

N1				●	●	●	●	●	●	●	●	●	N1
N2				●	●	●	●	●	●	●	●	●	N2
N3				●	●	●	●	●	●	●	●	●	N3
N4				●	●	●	●	●	●	●	●	●	N4
N5				○	○	○	○	○	○	○	○	○	N5
N6				●	●	●	●	●	●	●	●	●	N6
N7				●	●	●	●	●	●	●	●	●	N7
N8				●	●	●	●	●	●	●	●	●	N8
N9				●	●	●	●	●	●	●	●	●	N9
N10													N10

S1				●									S1
S2					●								S2
S3						●							S3
S4							●						S4
S5								●					S5
S6									●				S6
S7										●			S7
S8											●		S8

H1													H1
H2													H2
H3													H3
H4													H4