




Parametry skrawania AL B245

Cutting data AL B245

Z=2

AL



	Vc [m/min]	ød ₁ = 3 mm	ød ₁ = 4 mm	ød ₁ = 5 mm	ød ₁ = 6 mm	ød ₁ = 8 mm	ød ₁ = 10 mm	ød ₁ = 12 mm	ød ₁ = 14 mm	ød ₁ = 16 mm	ød ₁ = 18 mm	ød ₁ = 20 mm	
		fz [mm]	fz [mm]	fz [mm]	fz [mm]	fz [mm]	fz [mm]	fz [mm]	fz [mm]	fz [mm]	fz [mm]	fz [mm]	
P1													P1
P2													P2
P3													P3
P4													P4
P5													P5
P6													P6
P7													P7
P8													P8
P9													P9
P10													P10
P11													P11
P12													P12
P13													P13
P14													P14
M1													M1
M2													M2
M3													M3
K1													K1
K2													K2
K3													K3
K4													K4
K5													K5
K6													K6
N1	350	0,032	0,036	0,041	0,049	0,071	0,084	0,107	0,118	0,173	0,222	0,270	N1
N2	350	0,032	0,036	0,041	0,049	0,071	0,084	0,107	0,118	0,173	0,222	0,270	N2
N3	350	0,032	0,036	0,041	0,049	0,071	0,084	0,107	0,118	0,173	0,222	0,270	N3
N4	350	0,032	0,036	0,041	0,049	0,071	0,084	0,107	0,118	0,173	0,222	0,270	N4
N5													N5
N6													N6
N7	150	0,007	0,008	0,011	0,017	0,025	0,029	0,038	0,050	0,053	0,092	0,100	N7
N8	150	0,007	0,008	0,011	0,017	0,025	0,029	0,038	0,050	0,053	0,092	0,100	N8
N9	150	0,007	0,008	0,011	0,017	0,025	0,029	0,038	0,050	0,053	0,092	0,100	N9
N10													N10
S1													S1
S2													S2
S3													S3
S4													S4
S5													S5
S6													S6
S7													S7
S8													S8
H1													H1
H2													H2
H3													H3
H4													H4