



TABELA DOBORU FREZÓW VHM / SOLID CARBIDE END MILLS SELECTION TABLE

SUPERFAN										STL		
	440	R440	440N	R440N	440S	R440S	B440	540	R540	230	R230	430
Z	4	4	4	4	4	4	4	5	5	2	2	4
	VHM TiAIN	VHM TiAIN	VHM TiAIN	VHM TiAIN	VHM TiAIN	VHM TiAIN	VHM TiAIN	VHM TiAIN	VHM TiAIN	VHM TiAIN	VHM TiAIN	VHM TiAIN
HA	11-12	11-12	13-14	13-14	15-16	15-16	17	18-19	18-19	23	23	24
HB	11-12	11-12	13-14	13-14	15-16	15-16	17	18-19	18-19	23	23	24
Vc/fz	79	79	79	79	79	79	80	81	81	82	82	83



Strona / Page

Strona / Page

P1	•	•	•	•	•	•	•	•	•	•	•	•	P1
P2	•	•	•	•	•	•	•	•	•	•	•	•	P2
P3	•	•	•	•	•	•	•	•	•	•	•	•	P3
P4	•	•	•	•	•	•	•	•	•	•	•	•	P4
P5	•	•	•	•	•	•	•	•	•	•	•	•	P5
P6	•	•	•	•	•	•	•	•	•	•	•	•	P6
P7	•	•	•	•	•	•	•	•	•	•	•	•	P7
P8	•	•	•	•	•	•	•	•	•	•	•	•	P8
P9	•	•	•	•	•	•	•	•	•	•	•	•	P9
P10	•	•	•	•	•	•	•	•	•	•	•	•	P10
P11	•	•	•	•	•	•	•	•	•	•	•	•	P11
P12	•	•	•	•	•	•	•	•	•	•	•	•	P12
P13	•	•	•	•	•	•	•	•	•	•	•	•	P13
P14	•	•	•	•	•	•	•	•	•	•	•	•	P14
M1	•	•	•	•	•	•	•	•	•				M1
M2	•	•	•	•	•	•	•	•	•				M2
M3	•	•	•	•	•	•	•	•	•				M3
K1	•	•	•	•	•	•	•	•	•				K1
K2	•	•	•	•	•	•	•	•	•				K2
K3	•	•	•	•	•	•	•	•	•				K3
K4	•	•	•	•	•	•	•	•	•				K4
K5	•	•	•	•	•	•	•	•	•				K5
K6	•	•	•	•	•	•	•	•	•				K6
N1	○	○	○	○	○	○	○	○	○				N1
N2	○	○	○	○	○	○	○	○	○				N2
N3	○	○	○	○	○	○	○	○	○				N3
N4	○	○	○	○	○	○	○	○	○				N4
N5	○	○	○	○	○	○	○	○	○				N5
N6													N6
N7	○	○	○	○	○	○	○	○	○				N7
N8	○	○	○	○	○	○	○	○	○				N8
N9	○	○	○	○	○	○	○	○	○				N9
N10	○	○	○	○	○	○	○	○	○				N10
S1	○	○	○	○	○	○	○	○	○				S1
S2	○	○	○	○	○	○	○	○	○				S2
S3	○	○	○	○	○	○	○	○	○				S3
S4	○	○	○	○	○	○	○	○	○				S4
S5	○	○	○	○	○	○	○	○	○				S5
S6	○	○	○	○	○	○	○	○	○				S6
S7	○	○	○	○	○	○	○	○	○				S7
S8	○	○	○	○	○	○	○	○	○				S8
H1	○	○	○	○	○	○	○	○	○				H1
H2													H2
H3													H3
H4													H4