



TABELA DOBORU FREZÓW HSS / HSS END MILLS SELECTION TABLE

OPTI

	DIN-327	DIN-327	DIN-1889	DIN-844	DIN-844	DIN-844	DIN-844	DIN-844	DIN-844	DIN-845	DIN-845	
Z	2	2	2	4	4	4	4	1	1	4-8	4-8	
	HSSE/HSSE-PM - / AlTiN	HSS	HSSE	HSSE-PM - / AlTiN	HSSE	HSSE	HSSE/PM AlTiN	HSSE	HSSE	HSSE	HSSE	
HA								69	70	71	72	
HB	61-62	63	64	65	66	67	68					
Vc/fz	101-102	101-102	101-102	101-104	101-102	101-102	101-104	101-102	101-102	101-102	101-102	

P1	●	●	●	●	●	●	●			●	●	P1
P2	●	●	●	●	●	●	●			●	●	P2
P3	●	●	●	●	●	●	●			●	●	P3
P4	●	●	●	●	●	●	●			●	●	P4
P5	●	●	●	●	●	●	●			●	●	P5
P6	●	●	●	●	●	●	●			●	●	P6
P7	○	○	○	○	○	○	○			○	○	P7
P8	○	○	○	○	○	○	○			○	○	P8
P9	○	○	○	○	○	○	○			○	○	P9
P10	○	○	○	○	○	○	○			○	○	P10
P11	○	○	○	○	○	○	○			○	○	P11
P12	○	○	○	○	○	○	○			○	○	P12
P13	○	○	○	○	○	○	○			○	○	P13
P14	○	○	○	○	○	○	○			○	○	P14

M1	○	○	○	○	○	○	○			○	○	M1
M2	○	○	○	○	○	○	○			○	○	M2
M3	○	○	○	○	○	○	○			○	○	M3

K1	●	●	●	●	●	●	●			●	●	K1
K2	●	●	●	●	●	●	●			●	●	K2
K3	●	●	●	●	●	●	●			●	●	K3
K4	○	○	○	○	○	○	○			○	○	K4
K5	●	●	●	●	●	●	●			●	●	K5
K6	●	●	●	●	●	●	●			●	●	K6

N1								●	●			N1
N2								●	●			N2
N3								●	●			N3
N4								●	●			N4
N5								○	○			N5
N6	○	○	○	○	○	○	○	●	●	○	○	N6
N7	○	○	○	○	○	○	○	●	●	○	○	N7
N8	○	○	○	○	○	○	○	●	●	○	○	N8
N9	○	○	○	○	○	○	○	●	●	○	○	N9
N10												N10

S1												S1
S2												S2
S3												S3
S4												S4
S5												S5
S6	○	○	○	○	○	○	○			○	○	S6
S7	○	○	○	○	○	○	○			○	○	S7
S8	○	○	○	○	○	○	○			○	○	S8

H1	○	○	○	○	○	○	○			○	○	H1
H2	○	○	○	○	○	○	○			○	○	H2
H3												H3
H4	○	○	○	○	○	○	○			○	○	H4